

## GANCHO DE PESAJE

► Pantalla cristal líquido (LCD), que puede hacer La tara así como mostrar pesos brutos o netos.



CW10

CW50

CW100



MODELO		CW05	CW10	CW20C	CW30	CW50	CW100	CW150
Rango de medición	Kg	0-500	0-1000	0-2000	0-3000	0-5000	0-10000	0-15000
Precisión	Kg	0.2	0.5	1	1	2	5	5
Resolución	Kg	4	10	20	20	40	100	100
Dimensiones	A mm	315	315	315	315	315	355	355
	B mm	430	430	430	430	570	650	740
	C mm	540	540	540	540	710	820	930
Peso neto	Kg	5	11	11	15	21	50	58

